## ISO 9001:2008 Co.

## Rehsiff Scientific®

Manufacture & Importer of Laboratory Fine Chemicals, Diagnostic Kit & Lab wares

IODINE RESUBLIMED AR		
PRODUCT CODE	R01825	
SYNONYMS	-	
C.I. NO.	<del></del>	
CASR NO.	(7553-56-2)	
ATOMIC OR MOLECULAR FORMULA	$I_2$	
ATOMIC OR MOLECULAR WEIGHT	253.81	1
PROPERTIES	Readily sublimed having a violet vapour, soluble in alcohol, chloroform, ether, insoluble in water; a semiconductor.	l <sub>2</sub>
PARAMETER	LIMIT	
Description	Greyish violet brittle plates /scales/small crystals/granules w	ith metallic sheen.
Solubility (Take 2.5 gm sample + 5 gm KI + 5 gm Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub> in 85 ml of water)	A clear colourless solution is obtained.	
Identification	Passes test.	
Minimum Assay ( oxidimetric )	99.8%	
MAXIMUM LIMIT OF IMPURITIES		
Insoluble matter	Passes test.	
Non volatile matter	0.01%	
Chloride & Bromide (CI)	0.005%	
Note(s): 1] Assay (if applicable) method mentioned		
difficulties if inhaled. May cause allergic skin reaction. May damage the unbornchild. Causes damage to organs throug to aquatic life. Very toxic to aquatic life with long lasting eff Precautionary statements Prevention: Obtain special instructions before use. Do n understood. Do not breathe dust/fume/gas/mist/vapours/Wash thoroughlyafter handling. Do not eat, drink or smolventilated area. Contaminated work clothing should no	led. May cause allergic orasthmatic symptoms or breathing cause genetic defects. May cause cancer byinhalation. May the prolonged or repeated exposure byinhalation Very toxic fects.  ot handle until all safetyprecautions have been read and spray. Avoid breathing dust/fume/gas/mist/ vapours/spray. We when using this product. Use only outdoorsor in a well-t be allowed out ofthe workplace. Avoid release to the hing/ eye rotection/face protection. Use personal ntilation wear respiratory protection.  cor/physician if you feel unwell. IF ON SKIN: Wash with and keep at rest in a position comfortable forbreathing.	

**Disposal**: Dissolve the chemical to be disposed, in water and allow it to run to waste, diluting with large quantities of water. The quantitiesgreater than 10g should be dissolved in water and transferred to heavy metal waste drums for collection by specialist disposal company.

Hazard Pictogram(s) :-



advice/attention. If experiencing respiratory symptoms: Call a POISON CENTER or doctor/physician.



feel unwell. Get medical advice/attention if you feel unwell. Rinse mouth. If skin irritation or rash occurs: Getmedical



Replace Date 1 April 2023

Washcontaminated clothing before reuse. Collect spillage.

## : Regd Office, 201, MM Nagar, Ahmedabad (Gujarat)

Email: rehsiffscientific@gmail.com, www.rehsiffscientific.com

