

Rehsiff Scientific[®]

Manufacture & Importer of Laboratory Fine Chemicals, Diagnostic Kit & Lab wares

ACETALDEHYDE SOLUTION PRACT		
PRODUCT CODE R02002		
SYNONYMS		•
C.I. NO.		0
CASR NO.	75-07-0	
	C₂H₄O	
ATOMIC ORMOLECULAR FORMULA	- · · · · · · · · · · · · · · · · · · ·	¬₃∪ п
ATOMIC ORMOLECULAR WEIGHT PROPERTIES	44.05	
PARAMETER	LIMIT	
Description	A clear, almost colourless to pale yellow liquid. On prolong storage specially at lower temp., a white polymer may separate.	
Solubility	Miscible with water & alcohol.	
Assay (By acidimetric)	20 - 30% w/w	
Note(s) : Assay (if applicable) method mentioned.		
DANGER HAZARD STATEMENTS : May cause respiratory irritation. May causedrowsiness or diziness. Extremely flammable liquid and vapour. Harmful if swallowed. May be fatal if swallowed and enters airways. Causes mild skin irritation. Causes serious eye irritation. Suspected of causing cancer. Maydamage the unborn child. Harmful to aquatic life. PRECAUTIONARY STATEMENTS : PRECAUTIONARY STATEMENTS : PRECAUTIONARY STATEMENTS : Prevention :Obtain special instructions before use. Do not handle until all safetyprecautions have been read and understood. Keep away from heat/sparks/openflames/hot surfaces No smoking. Keep container tightly closed. Ground/bondcontainer and receiving equipment. Use explosion-proofelectrical/ventilating/lighting equipment. Use only non-sparking tools. Takeprecautionary measures against static discharge. Avoid breathing dust/fume/gas/mist/vapours/spray. Wash thoroughly after handling. Do not eat,drink or smoke when using this product. Use only outdoors or in a well- ventilatearea. Avoid release to the environment. Wear protective gloves/protectiveclothing/eye protection/face protection. Use personal protective equipment asrequired. Response :: SWALLOWED: Immediately call a POISON CENTER or doctor/physiciani. IF SWALLOWED: Call a POISON CENTER or doctor/physiciani fy ou feel unwell. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing, Rinse skin with water/shower. IF INHALED: Remove torsch air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, ifpresent and easy to do. Continue rinsing. IF exposed or concerned: Get medicaladvice/ attention. Disposal : Allow to evaporate in safe open area (applicable for small quantities). The chemical should be burnt in a chemical incinerator equipped with burner andscrubber. If the volumes are larger than 500ml and no incinerator and site ofewaporation in so ta vailable then transfer the waste chemical to waste solventdrum		

Replace Date 1 April 2023

